



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 12/05/2026

Incharge(s): Lal Singh

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-16	TRIPPED ON OLR	RESET DONE	05:40:00	05:45:00	
2	OHP	CO-29	OLR ACTED	RESET DONE	00:25:00	00:35:00	
3	OHP	CO-25	TRIPPED ON OLR	RESET DONE	02:00:00	02:10:00	
4	OHP	CO-26	TRIPPED ON OLR	RESET DONE	05:35:00	05:45:00	
5	CHP	CC-54	TRIPPED ON OLR	RESET DONE	23:50:00	00:00:00	
6	CHP	CC-131	TRIPPED ON OLR	RESET DONE	03:05:00 05:10:00	03:15:00 05:20:00	
7	CHP	CC-104 SCR-2	LT NOT WORKING M2 TRIPPED	RESET ... TRACK JAMMING .. INFORMED OPERATION	23:45:00	00:00:00	
8	CHP	CC-33 SCR-2	LT NOT WORKING PCRD OT	RESET	02:30:00	02:40:00	
9	CHP	CC-33 SCR-2	BC NOT RUNNING SIGNAL MISSING	LT DONE	00:00:00	00:10:00	
10	CHP	CC-104 SCR-6	BC STOPPING ... CJD ACTING	COAL CLEANING DONE THEN OK	03:00:00	03:20:00	
11	CHP	CC-33 SCR	BC NOT RUNNING ... SIGNAL MISSING	YARD INTERLOCK ZSS KEPT IN CKT	03:00:00	03:30:00	
12	CHP	CC-125	MPR TRIPPED ON OL	RESET DONE	03:50:00	04:00:00	
13	CHP	CC-44	MPD TRIPPED ON OL	RESET DONE	05:30:00	05:40:00	
14	CHP	CC-28	TRIPPED ON OLR	RESET DONE	05:40:00	05:45:00	
15	WT	OT-3	D1 TRIPPED ON ENCODER FAULT	RESET DONE	05:10:00	05:15:00	