



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 30/05/2026

Incharge(s): Saurabh Kumar Yadav

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 12(B)	stopped in pc	power recycled	02:15:00	02:30:00	
2	OHP	wobr 1 on CO 26	luff not working, control problem ,control wire loose connection in MPCB	control checked, spp reset, down limit bypass, wire tightened	02:00:00	02:30:00	
3	OHP	CO 26	olr acted	reset	02:55:00	03:05:00	
4	OHP	BRC on co 32	b/w 2 not running, backe plate stucked, chain loose	mechanical problem ,informed mechanical	01:05:00	01:20:00	
5	OHP	co 12(b)	showing red, no contact of aux contact not coming	tightened control cable, power recycle	03:45:00	03:55:00	
6	CHP	CC 33 scr2	LT not working, pcrd motor not running	reset	03:20:00	03:40:00	
7	CHP	CC 104 SCR6	b/c frequently stops ,zss cage stucked with coal	cage made free	04:10:00	04:20:00	
8	CHP	CC 54	motor tripped on olr 4 times	reset	01:45:00	01:50:00	
9	CHP	CC 131	or acted	reset	01:45:00	01:50:00	