



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 27/08/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	co 16 A	CS acted	CS cleaned	15:50:00	16:00:00	
2	OHP	CR 2	not healthy,oil flow not ok and Estop acted	reset,Estop released	20:15:00	20:25:00	
3	OHP	WOBR on co 26	slew not working,M10lr acted	reset	16:45:00	16:55:00	
4	OHP	brc on co8A	all drive not healthy,acb is in off	made it on	16:25:00	16:40:00	
5	CHP	CC 37 SCR3	B/C stopped in ZSS,probe cable old joint opened	cable jointed	20:00:00	20:12:00	
6	WT	CP1,2,3,4	no communication,wireless modem @CT bridge fallen and in LC10A modem to PLC no communication	modem replaced in near bridge an configuration done,than in LC 10 Aethernet cable cleaned POE to MODEM and PLC Ethernet cable unplugged and plugged	15:15:00	16:40:00	