



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 09/05/2026

Shift: C

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	BRC on CO 32	b/c not running,checked S/S in crmp side	s/s kept in chp side,oil level low informed mechanical	23:10:00	23:30:00	
2	OHP	CO 85	olr acted	reset	00:30:00	00:40:00	
3	OHP	co 16	olr acted	reset	04:00:00	04:10:00	
4	CHP	CC 32 scr4	b/w not running,	fault reset done	01:05:00	01:35:00	
5	CHP	CC 45	zss acted,cage problem	cage replaced	01:40:00	01:55:00	
6	CHP	CC 37 SCR3	bc not running,olr acted	reset	02:30:00	02:40:00	
7	CHP	CC 39 SCR7	slew not working,slew limit acted	released	03:20:00	03:30:00	
8	CHP	CC 125	olr acted mpd tripped	reset	03:55:00	04:00:00	
9	CHP	CC 51	mpd acted	reset	02:40:00	02:45:00	
10	CHP	CC 54	olr acted	reset	03:05:00	03:10:00	2 times
11	CHP	CC 58	olr acted	reset	04:00:00	04:15:00	2 times
12	WT	OT3	D2 tripped in saturation fault	reset	23:00:00	23:05:00	6 times
13	WT	OT 3	D2 tripped in encoder fault	reset	05:45:00	05:50:00	