वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 09/11/2026

Shift: A

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-17	Reported tripped	OLR acted.Reset done	07:30:00	07:40:00	
2	OHP	TBS on CO-20	Lt not taking place	M-4 tripped.Reset done	08:50:00	09:00:00	
3	OHP	CO-26	Reported tripped	OLR acted.Reset done	08:15:00	08:20:00	
4	OHP	CO-10A	Reported tripped	Reset done	09:40:00	09:50:00	
5	OHP	TBS on Co-21	Lt not taking place	PCRD tension acted.Released and tested okay	10:10:00	10:15:00	
6	OHP	BPC-1	Reported not running	Power recycle done	11:15:00	11:35:00	
7	OHP	CO-50	Reported tripped	OLR Acted.Reset done	09:45:00	09:55:00	
8	OHP	CO-26	Reported tripped	OLR Acted.Reset done	11:45:00	11:50:00	
9	OHP	TBS on CO-22	LT not taking place	PCRD cable fell onto chain from the drum.	13:40:00	14:00:00	To be adjusted
10	CHP	CC-51	MPD tripped	Reset done(2 times)	12:05:00	13:35:00	