



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 11/09/2026

Shift: B

Incharge(s): Nagendra Midde

| Sl No | Area | Equipment         | Problem                                                                   | Action                                             | From     | To       | Remarks |
|-------|------|-------------------|---------------------------------------------------------------------------|----------------------------------------------------|----------|----------|---------|
| 1     | OHP  | BRC ON CO 8A      | NO DRIVES RUNNING/ACB TRIPPING DUE TO RAIN WATER LEAKAGE IN BREAKER PANEL | ALL PANELS COVER WITH MATS                         | 15:30:00 | 17:00:00 |         |
| 2     | OHP  | BRC ON CO 8A      | BC NOT RUNNING/Y PHASE GOT EARTH FAULT AT PANEL O/G                       | POWER CABLE Y PHASE INSULATION DONE THEN TESTED OK | 17:15:00 | 18:50:00 |         |
| 3     | OHP  | CO 47             | ZSS ACTING                                                                | PROBE REPLACED THEN OK                             | 14:05:00 | 14:30:00 |         |
| 4     | OHP  | CR 1              | TRIPPED ON OLR                                                            | RESET DONE                                         | 19:15:00 | 19:20:00 |         |
| 5     | OHP  | CO 25             | TRIPPED ON OLR                                                            | RESET DONE                                         | 14:45:00 | 14:55:00 |         |
| 6     | OHP  | CO 34             | TRIPPED ON OLR                                                            | RESET DONE                                         | 20:00:00 | 20:05:00 |         |
| 7     | OHP  | CO 34             | BRS ACTING /CABLE EARTH FAULT                                             | BYPASSED AT CJB                                    | 16:25:00 | 16:40:00 |         |
| 8     | OHP  | CO 26             | TRIPPED ON OLR                                                            | RESET DONE                                         | 21:00:00 | 21:10:00 |         |
| 9     | OHP  | BRC ON CO 8A      | CT NOT TAKING PLACE/CHAIN GOT CUT                                         | INFORM TO OPERATION                                | 21:30:00 | 21:40:00 |         |
| 10    | CHP  | CC 54             | TRIPPED ON OLR                                                            | RESET DONE                                         | 14:20:00 | 14:25:00 |         |
| 11    | CHP  | CC 35 ZSS         | Cable cut Near module                                                     | Rejoined                                           | 15:00:00 | 15:15:00 |         |
| 12    | CHP  | SCR 5 on CC 32 LT | M2 trip                                                                   | Reset                                              | 18:45:00 | 19:00:00 |         |
| 13    | CHP  | CC 37 ZSS         | Cable got cut Near module                                                 | Connected properly                                 | 19:00:00 | 19:15:00 |         |
| 14    | CHP  | SCR on CC 36 B/C  | Slew 30 degree limit acted                                                | Released                                           | 19:40:00 | 19:55:00 |         |
| 15    | CHP  | CC 26 FLAP GATE   | TRIPPED ON MPCB                                                           | MADE ON                                            | 14:15:00 | 14:30:00 |         |



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 11/09/2026

Incharge(s): Nagendra Midde

Shift: B

| Sl No | Area | Equipment          | Problem                        | Action                                 | From     | To       | Remarks |
|-------|------|--------------------|--------------------------------|----------------------------------------|----------|----------|---------|
| 16    | CHP  | CC 202             | DRIVE TRIPPED ON OLR           | RESET DONE                             | 16:25:00 | 16:35:00 |         |
| 17    | CHP  | SCR 2 on CC 33     | Modem to plc not communicating | Ethernet connections tightened then ok | 19:30:00 | 20:00:00 |         |
| 18    | CHP  | Scr 3 on CC 36 B/C | Modem supply Neutral got cut   | Reconnected Properly                   | 20:00:00 | 20:20:00 |         |
| 19    | CHP  | CC 12              | BRS ACTED                      | RESET DONE                             | 18:25:00 | 18:30:00 |         |
| 20    | CHP  | CC 28              | FLAP GATE /MPCB TRIPPED        | MADE ON                                | 15:45:00 | 15:55:00 |         |