



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 26/09/2026

Shift: B

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	BRC on CO-30	C/S acted	Due to jamming	14:35:00	14:50:00	Informed to operation
2	OHP	WOBR on CO-6A	LT not taking place	M-6 tripped(2 times).Reset done	16:30:00 20:00:00	16:45:00 20:10:00	
3	OHP	BRC on CO-32	LT not taking place	PCRD tension acted and skew limit acted	17:10:00 18:25:00 21:00:00	17:20:00 18:35:00 21:20:00	
4	OHP	TT-4	Reported position indication not coming	Wire came out of TB due to material spillage.Wire connected and tested okay	17:25:00	17:45:00	
5	OHP	VS-10	Reported tripped	MPCB tripped(2 times).Given clearance on single motor due to bearing problem	18:55:00	19:05:00	Motor to be replaced
6	OHP	CO-29	Reported tripped	OLR acted.Reset done	21:35:00	21:40:00	
7	OHP	BRC on CO-30	Ct not taking place	MCCB tripped.Made on	21:30:00	22:00:00	
8	OHP	VS-1	Reported tripped	OLR acted.Reset done	17:10:00	17:15:00	
9	OHP	VS-2	Reported tripped	OLR acted.Reset done	18:55:00	19:10:00	
10	CHP	SCR-4 on CC-111	Lt not taking place	PCRD tension acted.Released	19:55:00	20:10:00	