



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL GENERAL SHIFT REPORT

Date: 28/05/2026

Area: OHP

Equipment	Job
yard stacking conveyors	BSS inspection is done, found to be in circuit. co-19 bss switch chp side handle is missing.