



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 16/06/2026

Shift: C

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 25	OLR acted	reset	23:15:00	23:20:00	
2	OHP	CO 26	OLR acted	reset	01:15:00	01:25:00	
3	OHP	WOBR on CO 29	Luffing not working,olr atced	reset	01:10:00	01:20:00	
4	OHP	TBS on Co 20	LT not working,gearbox chain fallen	informed mechanical	22:25:00	22:35:00	
5	OHP	BRC on CO 28	B/w 1 not rotating,OLR acted	reset	04:35:00	04:50:00	
6	OHP	TBS on CO 20,23,24	no power ,control tripped,(acb triped of only CO 20 TBS)	control made on,acb made on of TBS 20	05:30:00	06:00:00	
7	CHP	CC 32 SCr2	Lt not working,pcrd drum sensor not rotating	reset it	00:45:00	00:55:00	
8	CHP	C C 125	mpd acted	reset	00:50:00	00:55:00	
9	CHP	CC 112 SCR 8	b/w not running,oil level low,O/P fuse in PLC panel blown of k25	mechanical top up oil,fuse replaced	04:00:00	04:40:00	
10	CHP	CC 105 SCR10	all drive not working,acb tripped	made it on	05:30:00	05:40:00	
11	CHP	CC 44	olr acted	reset	05:45:00	05:50:00	
12	WT	OT 3	D2 tripped in encoder fault,brake problem	reset,mechanical adjusted brake	23:30:00	23:45:00	3 times