



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 04/10/2026

Shift: A

Incharge(s): Amit Roy

| Sl No | Area | Equipment     | Problem                     | Action                                                                                             | From     | To       | Remarks                |
|-------|------|---------------|-----------------------------|----------------------------------------------------------------------------------------------------|----------|----------|------------------------|
| 1     | OHP  | WOBR on CO-25 | NO operations taking place  | Luffing emergency acted.Luff up done by pressing bypass button and control made on and tested okay | 06:35:00 | 07:00:00 |                        |
| 2     | OHP  | BRC on CO-8A  | Reported B/W-1 not rotating | Chain fallen.                                                                                      | 07:15:00 | 07:30:00 | Informed to mechanical |
| 3     | OHP  | WOBR on CO-26 | Slewing not taking place    | Limit switch stuck.Made free                                                                       | 08:00:00 | 08:15:00 |                        |
| 4     | OHP  | WOBR on CO-25 | Slewing not taking place    | Limit switch stuck.Made free                                                                       | 11:00:00 | 11:20:00 |                        |
| 5     | OHP  | CO-32         | BRS problem                 | Return high not reaching CJB.Cable problem.Bypassed and after cable changed kept in line           | 11:00:00 | 11:10:00 | Kept in line at 1.50pm |
| 6     | OHP  | CO-29         | Reported tripped            | OLR acted.Reset done                                                                               | 11:40:00 | 11:45:00 |                        |
| 7     | OHP  | BRC on CO-30  | Ct not taking place         | Drive tripped.Reset done                                                                           | 12:45:00 | 13:00:00 |                        |
| 8     | OHP  | BRC on CO-8A  | Lt not taking place         | M-2,M-3 tripped.Reset done                                                                         | 12:45:00 | 13:05:00 |                        |
| 9     | CHP  | R-1 on CC-39  | B/C not running             | Communication problem.ZSS was in line.Communication bit bypassed and tested okay                   | 08:40:00 | 08:50:00 |                        |
| 10    | CHP  | R-1 on Cc-39  | Lt not taking place         | PCRD cam switch problem due to coal stuck.Overhauling done and tested okay                         | 09:50:00 | 10:00:00 |                        |
| 11    | CHP  | CC-125        | Reported tripped            | OLR Acted.Reset done                                                                               | 12:25:00 | 12:30:00 |                        |



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 04/10/2026

Incharge(s): Amit Roy

Shift: A

| Sl No | Area | Equipment | Problem          | Action                                     | From     | To       | Remarks                          |
|-------|------|-----------|------------------|--------------------------------------------|----------|----------|----------------------------------|
| 12    | WT   | OT-3      | Reported tripped | D-1 tripped on encoder-43 fault.Reset done | 12:00:00 | 12:10:00 | No delay as rakes were not there |