



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 07/06/2026

Incharge(s): Amit Roy

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CR-1A	Reported Lub pump tripping on outside oil flow	Electrical side okay.Oil flow not proper	01:00:00	01:30:00	Informed to mechanical
2	OHP	CO-26	Reported tripped	OLR acted.Reset done	22:50:00	23:00:00	
3	OHP	BRC on CO-32	LT not taking place	PCRD tension acted.Released	00:45:00	01:00:00	
4	OHP	CO-29	Reported tripped	OLR acted.Reset done	03:00:00 04:00:00	03:10:00 04:10:00	
5	OHP	BRC on CO-32	B/W-1,2 not running	Wrong complaint	05:10:00	05:25:00	
6	CHP	CC-40	Reported tripped	OLR acted.Reset done	01:15:00	01:25:00	
7	CHP	CC-33 SCR-2	B/W not running	Drive tripped.Reset done	01:40:00	01:55:00	
8	CHP	CC-112 SCR-8	B/C not running	Electrical side okay.Belt not moving due to heavy material on belt	04:15:00	04:30:00	
9	CHP	Cc-38 SCR-5	LT not taking place	M5 OLR acted.Reset done	04:40:00	04:50:00	