



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 05/09/2026

Incharge(s): Amit Roy

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WOBR on CO-25	Reported B/C not running	Checked and found control tripped due to luff down limit acted. Control made on and luff up done and tested okay	20:00:00	20:20:00	
2	OHP	CO-25	Reported tripped	OLR acted. Reset done	21:00:00	21:05:00	
3	CHP	Cc-58	Reported tripped	Tripped on current sp fault. Reset done	15:30:00 18:30:00	15:45:00 18:45:00	
4	CHP	Cc-18	Reported failed to start	Checked and found control voltage dropping when command given. PC bypassed and checked and tested okay	14:40:00	15:30:00	
5	CHP	CC-19	Reported tripped	Failed to start. PC bypassed and tested okay	18:50:00	19:05:00	no delay
6	CHP	CC-28 FG	Reported tripped	OLR acted. Reset done	21:30:00	21:35:00	