RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 28/10/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 16	OLR ACTED	RESET	14:00:00	14:15:00	
2	OHP	co 111	pc acted, not getting reset	reset it	17:20:00	17:35:00	
3	OHP	co 26	olr acted	reset	19:15:00	19:25:00	
4	OHP	rsco 6a	olr acte	reset	20:35:00	20:45:00	
5	OHP	co 34	olr acted	reset	20:20:00	20:30:00	2 times
6	OHP	WOBR on CO 25	slew not stopping after giving stop cmd	wrong complaint,checked both R and L slew than given stop cmd it is stopped	21:10:00	21:25:00	
7	OHP	CBMS on CO 6A	MCCB tripped due to motor problem	motor hot blowing done	21:20:00	21:45:00	
8	CHP	SCR1	b/c stopped after b/w running,zss high fuse blown,NO ,Nc contact in contactor loose connection	tightened,fuse replaced	14:00:00	14:15:00	
9	CHP	CC 48	E PB problem	replaced	16:45:00	17:00:00	
10	CHP	cc 39	BC position not coming, magnetic switch problem	bypass in I/o rack	17:00:00	17:15:00	
11	CHP	CC 33 SCR2	Lt not working,drum sensor acted	released	17:50:00	18:05:00	
12	WT	OT1	D1 tripped in ocn fault	reset	17:30:00	17:40:00	