



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 27/04/2026

Incharge(s): Amit Roy

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-26	Reported tripped	OLR acted.Reset done	23:25:00	23:35:00	
2	OHP	WOBR on CO-29	LT not taking place	M-4 tripped.Made on and tested okay	00:30:00	00:40:00	
3	CHP	CC-27	Reported tripped	OLR acted.Reset done	04:00:00	04:10:00	
4	CHP	CC-31 SCR-1	No operations taking place	Checked and found PLC output card problem.Replaced and tested okay	22:00:00	22:55:00	
5	CHP	CC-106 SCR-6	Reported no power	High speed relay tripped in LC-2.Made on and tested okay	03:10:00	03:30:00	
6	CHP	CC-39 SCR-7	LT not working	Drive tripped.Reset done	05:25:00	05:35:00	
7	CHP	CC-51	MPD tripped	Reset done	01:50:00	01:55:00	
8	CHP	CC-131	PC acted	PC released and tested okay	00:10:00	00:20:00	
9	CHP	CC-117	Reported TT CS not healthy	Wrong complaint	02:15:00	02:35:00	
10	CHP	CC-58	Reported tripped	Tripped 2 times and found MCCB y phase not coming.Replaced with spare and tested okay	03:40:00	04:30:00	