



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL GENERAL SHIFT REPORT

Date: 30/05/2026

Area: OHP

Equipment	Job
co-19	panel side blowing / inspection is done.
All Yard HT couplers area	Space heaters inspection is done, found ok.
tbs-7 on co-19	panels blowing is done, terminal tightening is done.
wobr-2 on repair bay	welding machine supply and lighting is provided as required.
BRC-2 on co-30	Yard ZSS interlock arrangement , both sides is modified and testing is done. HT transformer Oil leak is observed.
co-16 mechanical BRS	probe is changed and restored its working.
co-1a zss and brs	checking is done and restored brs in circuit.
1-141lc4 ground floor, 1-15lc2, llds-6 RIO racks	PPM is done.
aso-3	supply cable permanent routing is done and termination is done in PJB's
co11a BRS	module , sensors replaced and kept in circuit.