



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 30/05/2026

Incharge(s): Saurabh Kumar Yadav

Shift: C

| Sl No | Area | Equipment       | Problem                                                                  | Action                                                        | From     | To       | Remarks |
|-------|------|-----------------|--------------------------------------------------------------------------|---------------------------------------------------------------|----------|----------|---------|
| 1     | OHP  | CO 12(B)        | stopped in pc                                                            | power recycled                                                | 02:15:00 | 02:30:00 |         |
| 2     | OHP  | wobr 1 on CO 26 | luff not working, control problem ,control wire loose connection in MPCB | control checked, spp reset, down limit bypass, wire tightened | 02:00:00 | 02:30:00 |         |
| 3     | OHP  | CO 26           | olr acted                                                                | reset                                                         | 02:55:00 | 03:05:00 |         |
| 4     | OHP  | BRC on co 32    | b/w 2 not running, backe plate stucked, chain loose                      | mechanical problem ,informed mechanical                       | 01:05:00 | 01:20:00 |         |
| 5     | OHP  | co 12(b)        | showing red, no contact of aux contact not coming                        | tightened control cable, power recycle                        | 03:45:00 | 03:55:00 |         |
| 6     | CHP  | CC 33 scr2      | LT not working, pcrd motor not running                                   | reset                                                         | 03:20:00 | 03:40:00 |         |
| 7     | CHP  | CC 104 SCR6     | b/c frequently stops ,zss cage stucked with coal                         | cage made free                                                | 04:10:00 | 04:20:00 |         |
| 8     | CHP  | CC 54           | motor tripped on olr 4 times                                             | reset                                                         | 01:45:00 | 01:50:00 |         |
| 9     | CHP  | CC 131          | or acted                                                                 | reset                                                         | 01:45:00 | 01:50:00 |         |