



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 09/06/2026

Incharge(s): Saurabh Kumar Yadav

Shift: B

| Sl No | Area | Equipment    | Problem                                                                                                            | Action                                                                                                 | From                 | To                   | Remarks |
|-------|------|--------------|--------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------|----------------------|----------------------|---------|
| 1     | OHP  | BRC on CO 32 | b/w 1 and 2 stopped in ZSS                                                                                         | ZSS bypassed                                                                                           | 20:30:00             | 22:10:00             |         |
| 2     | OHP  | co 26        | olr acted                                                                                                          | reset                                                                                                  | 20:30:00             | 20:40:00             |         |
| 3     | OHP  | co 29        | olr acted                                                                                                          | reset                                                                                                  | 19:20:00             | 19:30:00             |         |
| 4     | CHP  | CC 51        | mpd tripped                                                                                                        | reset                                                                                                  | 17:30:00             | 17:35:00             |         |
| 5     | CHP  | CC 131       | olr acted                                                                                                          | reset                                                                                                  | 18:20:00             | 18:25:00             |         |
| 6     | CHP  | CC 44        | motor tripped                                                                                                      | reset                                                                                                  | 19:50:00             | 20:00:00             |         |
| 7     | WT   | OP 2         | no movement,brake binding, pusher having heavy vibration,cascade contactor moving and fixed contact tip got welded | cascade contactor replaced,control checked found all ok,rack decoupled pusher moved smoothly decoupled | 18:45:00<br>19:45:00 | 19:15:00<br>20:30:00 |         |