



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 01/10/2026

Incharge(s): Amit Roy

Shift: A

| Sl No | Area | Equipment      | Problem                  | Action                                                 | From     | To       | Remarks                |
|-------|------|----------------|--------------------------|--------------------------------------------------------|----------|----------|------------------------|
| 1     | OHP  | WOBR on CO-29  | Luff up not taking place | Oil level low                                          | 07:10:00 | 07:30:00 | Informed to mechanical |
| 2     | OHP  | CO-33M         | Reported tripped         | OLR acted.Reset done                                   | 11:50:00 | 11:55:00 |                        |
| 3     | CHP  | CC-51A         | Reported tripped         | OLR acted.Reset done(2 times)                          | 08:45:00 | 09:00:00 |                        |
| 4     | CHP  | SCR-7 on CC-40 | B/C not running          | Communication problem.ZSS kept in line and tested okay | 11:10:00 | 12:00:00 |                        |
| 5     | CHP  | SCR-6 on CC-38 | B/C not running          | Discharge chute CJD acted due to jamming               | 12:05:00 | 12:20:00 | Informed to operation  |
| 6     | CHP  | CO-25,26,27    | BRS acted                | Fuse blwon at I/O rack.Replaced and tested okay        | 10:40:00 | 11:15:00 |                        |
| 7     | WT   | CP-2           | Reported not moving      | D-1 tripped due to brake binding                       | 11:35:00 | 12:00:00 | Informed to operation  |