वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 21/10/2026

Shift: B

Incharge(s): Nagendra Midde

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS on CO 24 Left Luff	OLR acting due to break pad problem	Informed to mech	19:15:00	19:30:00	
2	OHP	CO 34	OLR acted	Reset	19:30:00	20:00:00	2 times
3	OHP	S2 on CC 35 Lt	Control MCB trip in pcrd panel	Made it on	20:20:00	20:35:00	
4	OHP	No voltage in LINE PT	For Incomer 1 in 1-2LBDS8	Bus coupler made it on	20:45:00	21:00:00	
5	CHP	SCR 5 on CC 31 LT	Drive trip	Reset	18:05:00	18:20:00	
6	CHP	CC 107 BRS	Not resetting	Sensors cleaned then ok	19:35:00	19:45:00	
7	CHP	CC 203	OLR acted	Reset	14:30:00	19:10:00	2 times
8	CHP	CC 21 CD	OLR acted	Reset	15:15:00	15:20:00	