



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 05/06/2026

Shift: C

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CC-125	Reported tripped	OLR acted.Reset done	00:20:00 03:25:00 05:20:00	00:30:00 03:30:00 05:25:00	
2	OHP	TBS on CO-21	LT not taking place	PCRD tension acted.Released	03:35:00	03:50:00	
3	OHP	CO-11A	BRS acted	Due to belt piece	02:30:00	02:40:00	Informed to operation
4	CHP	Cc-45	Reported fail to start	Checked and found IM module both faulty.Profibus connectors removed and again put back.Redundancy line module bus fault found and kept out of line and tested okay	23:00:00	23:30:00	
5	CHP	Cc-104 SCR-6	LT and slew not taking place	Slew olr acted.Reset done LT PCRD tension acted due to tack jamming	23:55:00	00:00:00	Inforemed to operation
6	CHP	CC-112 SCR-8	BC not running	Cage stuck with coal.Made free	02:40:00	03:05:00	
7	CHP	CC-38 SCR-5	LT not taking place	M-5 acted due to track jamming.Reset done	03:15:00	03:25:00	
8	CHP	CC-29	ZSS acted	Cage stuck.Made free	03:55:00	04:00:00	
9	CHP	Cc-51	MPD tripped	OLR acted.Reset done	04:00:00 23:25:00	04:05:00 23:35:00	
10	CHP	Cc-115	BRS not working	Sensor cleaning done and tested okay	23:40:00	00:00:00	
11	WT	OT-4	Reported tripped	D-2 tripped on PGEF-4 fault.Reset done	02:10:00	02:15:00	