



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 30/04/2026

Shift: B

Incharge(s): Amit Roy

| Sl No | Area | Equipment     | Problem                        | Action                                                                           | From     | To       | Remarks               |
|-------|------|---------------|--------------------------------|----------------------------------------------------------------------------------|----------|----------|-----------------------|
| 1     | OHP  | CO-41A        | Reported BRS acting frequently | Belt side cutting found and material spilling.                                   | 17:10:00 | 17:20:00 |                       |
| 2     | OHP  | CO-6A         | Reported tripped               | OLR acted.Reset done                                                             | 16:15:00 | 16:25:00 |                       |
| 3     | OHP  | WOBR on CO-25 | LT not taking place            | Drive tripped.Reset done                                                         | 15:05:00 | 15:20:00 |                       |
| 4     | OHP  | CO-34         | Reported BRS acting frequently | Checked and found BRS is okay.Belt hole found and informed the same to operation | 19:55:00 | 20:15:00 | Informed to operation |
| 5     | CHP  | Cc-39 SCR-7   | B/C not running                | OLR acted.Reset done                                                             | 19:15:00 | 19:30:00 |                       |
| 6     | CHP  | Cc-107        | Reported tripped               | OLR acted.Reset done                                                             | 21:00:00 | 21:05:00 |                       |
| 7     | CHP  | Cc-125        | Reported tripped               | OLR acted.Reset done                                                             | 21:10:00 | 21:15:00 |                       |
| 8     | CHP  | Cc-51         | MPD tripped                    | Reset done                                                                       | 17:05:00 | 17:10:00 |                       |
| 9     | CHP  | Cc-28         | Reported tripped               | OLR acted.Reset done                                                             | 17:30:00 | 17:40:00 |                       |
| 10    | CHP  | CC-18         | ZSS acting                     | Cage got struck with material.Made free and tested okay                          | 18:15:00 | 18:30:00 |                       |
| 11    | WT   | OP-4          | Reported not moving            | D-4 tripped during coupling time.Reset done                                      | 15:35:00 | 15:50:00 |                       |
| 12    | WT   | OT-3          | Reported tripped               | D-2 tripped on encoder 43 fault.Reset done                                       | 16:15:00 | 16:20:00 |                       |
| 13    | WT   | OT-4          | LS-2 problem                   | Striker got bent.Bypassed                                                        | 20:40:00 | 20:50:00 |                       |