



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 28/05/2026

Incharge(s): G Eswara Rao

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 26	TRIPPED ON OLR	RESET DONE	06:25:00	06:30:00	
2	OHP	BRC ON CO 8A	LT NOT TAKING PLACE/CONTROL OFF	CONTROL MADE ON AT CD	07:55:00	08:15:00	
3	CHP	CC 51	MPD TRIPPED ON OLR	RESET DONE	08:40:00	08:45:00	
4	CHP	SCR 1 ON CC31	LT NOT TAKING PLACE/M 7 OLR ACTED	RESET DONE	09:25:00	09:40:00	
5	CHP	SCR 2 ON CC33	SLEW NOT TAKING PLACE/DRIVE TRIPPED ON OLR	RESET DONE	11:30:00	11:45:00	
6	CHP	SCR 5 ON CC38+	BC STOPPING DUE TO SIGNAL MISSING	LT REVERSE DONE .THEN OK	11:50:00	12:10:00	
7	WT	OT 3	DRIVE 2 TRIPPED ON ENCODER FAULT9(43)	RESET DONE 2 TIMES	08:50:00 09:05:00	08:55:00 09:10:00	
8	WT	OP 9	MIDDLE PAD C CLAMP BEND WHILE AFTER RAKE MAINTANCE	C CLAMP REPLACED .	12:00:00	12:10:00	NO DELAY