



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 07/05/2026

Shift: C

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	co 26	olr acted	reset	22:30:00	22:40:00	
2	OHP	co 25	olr acted	reset	01:52:00	02:00:00	
3	OHP	wobr on co 29	BW motor not running, full jamming, motor fully heated	megger done all value ok	05:00:00	05:30:00	to be checked after motor cooled down
4	CHP	CC 26A	olr acted	reset	01:35:00	01:40:00	
5	CHP	CC 37 SCR3	slew not working	wrong complaint, operated not operated lever fully	02:02:00	02:15:00	
6	CHP	CC 47	stopping in ZSS, cage stucked with coal	cage made free	02:30:00	02:40:00	
7	CHP	CC 58	olr acted	reset	05:40:00	05:50:00	
8	CHP	CC 33 scr2	luff not working, PS2 bit not coming	bypass in i/o rack	03:50:00	04:00:00	
9	CHP	CC 36 R1	b/c not working, olr acted, bw stucked in coal	reset	04:45:00	04:55:00	
10	WT	OP4	no movement, no power, acb tripped in LC, D5 spark observed	D5 coil connection removed and given clearance, d5 tb cover open and bolt tightened and kept in ckt	22:30:00	23:00:00	
11	WT	OP5	d5 OLR acted	reset	00:40:00	00:48:00	