RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 14/11/2026

Shift: A

Incharge(s): M Kailash

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS ON CO-22	No drives running. Found control is in OFF condition	Made ON from operator cabin	06:25:00	06:35:00	operator mistake
2	OHP	CO-26	overload acted	Reset done	12:45:00	12:55:00	
3	OHP	TBS ON CO-20	LT not stopping due to brake not holding	informed to mechanical for adjustment	12:35:00	12:45:00	
4	CHP	CC-51	MPR acted to stop feeding conveyor	reset done	06:10:00	13:30:00	7 times
5	CHP	CC-131	overload acted	Reset done	06:40:00	06:45:00	
6	WT	OP-4	Movement stopping in between. D-6 rotor contactor getting stuck	Contactor opened and cleaned. Made OK	09:20:00	09:35:00	
7	IOSA	BRC	LT not running in AUTO. checked and found machine getting stuck up due to material overflow near tracks	Machine made reverse and checked the operation and found OK. Informed to operation	07:50:00	08:10:00	