



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 01/10/2026

Shift: C

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	co 26	OLR acted	reset	22:10:00	22:20:00	
2	OHP	co 10A	OLR acted	reset	22:50:00	23:00:00	
3	OHP	CO 48	OLR acted	reset	01:40:00	01:50:00	
4	OHP	co 32	BRS not healthy, control ckt unhealthy, loose connection, aux relay chattering sound coming	control wire rewired and BRS checked found ok	01:30:00	01:40:00	
5	OHP	co 58	zss acted, module problem	module replaced	05:50:00	06:10:00	
6	CHP	CC 31 scr1	LT not working, track jamming	, informed to operation	23:10:00	23:20:00	
7	CHP	CC 39 R1	b/c not running, olr acted	reset	03:05:00	03:20:00	
8	CHP	CC 39 R1	b/c not running, communication problem,	comm bit kept in ckt, modem to ethernet cable connected	03:55:00	04:10:00	
9	CHP	CC 104 SCR9	slew and b/w not working, control mcb tripped	made it on	04:20:00	04:35:00	
10	CHP	CC 131	motor tripped in oLR	reset	04:25:00	04:30:00	
11	CHP	CO 25	OLR acted	reset	23:25:00	23:30:00	