



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 28/04/2026

Shift: B

Incharge(s): Lal Singh

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-67	OLR TRIPPED	RESET DONE	15:45:00	15:55:00	
2	OHP	TBS ON CO-5A	NO DRIVES WORKING	CONTROL WAS IN OFF MADE ON	14:30:00	14:50:00	
3	OHP	CO-34	BRS NOT HEALTHY	IO RACK LOOSE CONNECTION RECTIFIED (IN BYPASS)	15:35:00	15:55:00	
4	OHP	BRC ON CO28	CT LOCAL REMOTE SWITCH LOOSE	FIXED	18:00:00	18:20:00	
5	OHP	CO-26	OLR ACTED	RESET DONE	19:50:00	20:00:00	
6	OHP	OP-8	NOT MOVING	LS-2 BYPASSED THEN OK	19:30:00	19:35:00	
7	OHP	RSCO-10A	CHUT SENSOR NOT HEALTHY ... HIGH FUSE BLOWING IN CJB	EARTH FAULT IDENTIFIED IN ZSS MODULE AND RECTIFIED	21:30:00	22:10:00	
8	CHP	CC-39 SCR-7	LT DRIVE TRIPPED AND PCRD OT ACTED	RESET	16:30:00 17:00:00	16:40:00 17:15:00	
9	CHP	CC-105 SCR-10	SLEW 30 DEGREE ACTED	RELEASED	18:30:00	18:40:00	
10	CHP	CC-33 SCR-5	LUFF NOT WORKING .. OIL LEAKAGE	INFORMED MECH	20:50:00	21:05:00	
11	CHP	CC-132	PC ACTED	CHECKED PC WAS IN ACTED CONDITION ... RESET DONE	19:00:00	19:30:00	
12	CHP	CC-51	FEEDING CON STOPPED DUE TO OLR 2 TIMES	RESET DONE	21:00:00	21:40:00	
13	CHP	CC-52	FEEDING CON STOPPED DUE TO OLR	RESET DONE	18:00:00	18:30:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 28/04/2026

Incharge(s): Lal Singh

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
14	WT	OP-5	D5 OLR ACTED	RESET DONE	19:20:00	19:30:00	
15	WT	OP-4	D3 TRIPPED	RESET DONE	15:10:00	15:20:00	