



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 27/04/2026

Shift: A

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	brc on co 8a	It not taking place/thurster brake problem	brake connection disconnected at tb and brake loosen then given clearance	07:40:00	08:00:00	
2	CHP	CC 26	NOT RUNNING IN HEALTHY/NOT SELECTED ROUTE FOR TT OR DIRECT	SELECTED DIRECT	07:00:00	08:15:00	
3	CHP	SCR 1 ON CC 31	YARD SIGNAL MISSING	COMMUNICATION PROBLEM/RECYCLED CONTROL FOR PLC AND LT DONE	08:15:00	08:40:00	
4	CHP	CC 26	JOD (mech brs) not working /swith problem	bypassed at i/o rack	07:30:00	07:45:00	again kept in ckt at 1045am
5	CHP	cc 103	brs acting/	bypassed for ope.requirement	07:15:00	07:30:00	rectified to be kept in ckt
6	CHP	CC 51	TRIPPED ON OLR IN MPD	RESET DONE	10:30:00	10:35:00	
7	CHP	cc216	tripped on olr in mpd	reset done	10:15:00	10:25:00	
8	CHP	scr 6 on cc 106	no drives running/high speed relay tripped at lc-2	reset done	10:30:00	10:40:00	
9	WT	OP 4	FORWARD/REVERSE NOT TAKING PLACE/D3 TRIPPED WHILE COUPLING TIME	RESET DONE	10:15:00	10:25:00	