



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 09/08/2026

Incharge(s): P Venkat Kiran,P Venkat Kiran

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	co-14	mccb was tripping on start	LM400, MCCB failed, replaced with spare module, motor meggered, tb checked found ok and trail run taken.	06:40:00	07:30:00	Found balanced currents, 102A.
2	CHP	CC 14	Olr Acted Due to Jamming in Tail end	Reset and Informed to oprn	12:20:00	12:30:00	
3	CHP	CC 52	Feeding conv OLR acted	Reset	11:15:00	12:15:00	2 times
4	IOSA	TBS	RBC zss probe not working	probe replaced and tested	10:20:00	10:20:00	no delay