



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 29/05/2026

Incharge(s): Amit Roy

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WOBR on CO-29	Reported luffing not taking place	Luff down limit acted.	06:50:00	07:00:00	
2	OHP	CO-26	Reported tripped	OLR acted.Reset done	10:45:00	10:55:00	
3	OHP	WOBR on CO-29	Luffing not taking place	OLR acted.Reset done	11:40:00	11:55:00	
4	OHP	CO-22	Reported E-stop not releasing	Elmax connector problem at CJB.Replaced and tested okay	12:30:00	12:50:00	
5	OHP	BF-2A	ZSS acting	Probe adjusted and tested okay	13:00:00	13:20:00	
6	OHP	RSCO-6A(C/D)	Reported tripped	OLR acted.Reset done	13:30:00	13:40:00	
7	CHP	CC-17	ZSS acting	Probe damaged.Replaced and tested okay	10:40:00	10:50:00	
8	CHP	Cc-21(C/D)	Reported tripped	OLR acted.Reset done	09:20:00	12:50:00	
9	CHP	CC-112,113	Reported no power	CM-36 breaker tripped.Made on	07:30:00	07:45:00	