वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 15/10/2026

Shift: B

Incharge(s): M Kailash

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS ON CO-22	Right luff not working. Overload acted	Reset done	14:15:00	14:30:00	
2	OHP	CO-10A	Overload acted	reset done	15:15:00	15:20:00	
3	OHP	BRC ON CO-8A	Oil pump feedback fault. Control desk Reset not done	reset done and made OK	17:30:00	17:45:00	
4	OHP	CO-11A	BRS acting frequently. Checked with empty belt and with load	No complaint found.	17:30:00	18:30:00	No delay
5	OHP	BRC ON CO-32	LT complaint. PCRD tension acted	Released and made OK	20:40:00	20:50:00	
6	OHP	BRC ON CO-8A	Oil temperature high trip. Found Bucket wheel pump contactor welded and MCCB tripped	Tips changed from spare feeder and tested OK	20:30:00	21:10:00	
7	OHP	WOBR ON CO-29	Luff not working.	Checking is under progress	21:10:00	22:00:00	
8	OHP	CO-26	Overload acted	Reset done	17:00:00 21:30:00	17:10:00 21:45:00	
9	CHP	CC-51	Feeding conveyor tripped on overload	Reset done	17:30:00 18:20:00	17:35:00 18:25:00	
10	CHP	CC-52	Tripped on overload	Reset done	21:00:00	21:05:00	
11	IOSA	WOBR ON OC-17A	ZSS probe failed	Probe changed	15:50:00	16:10:00	