वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 16/10/2026

Shift: B

Incharge(s): G Eswara Rao

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 24	BRS WAS IN BYPASSED	KEPT IN CKT	17:00:00	17:10:00	
2	OHP	TBS ON CO 21	BC NOT RUNNING/OLR ACTED DUE TO JAMMING	RESET DONE	17:25:00	17:40:00	
3	OHP	CO 25	TRIPPED ON OLR	RESET DONE	17:20:00 19:00:00	17:35:00 19:10:00	
4	OHP	BRC ON CO 31	BC NOT RUNNING/OLR ACTED	RESET DONE	20:05:00	20:20:00	
5	OHP	CO 29	TRIPPED ON OLR	RESET DONE	20:25:00	20:30:00	
6	CHP	scr on cc40	bc not running/mpd tripped on e207 fault	reset done	16:25:00	16:35:00	
7	CHP	SCR 1 ON CC31	LUFFING NOT TAKING PLACE/DOWN LIMIT ACTED	BYPASSED FOR OPERATION REQUIREMENT AGAIN KEPT IN CKT	17:40:00 17:40:00	21:00:00 17:50:00	
8	CHP	CC 107	BSS RF ACTED/NOT GETTING RESET	BYPASSED AT PLC	19:10:00	19:20:00	
9	CHP	CC 131	TRIPPED ON OLR	RESET DONE	20:05:00	20:10:00	
10	CHP	SCR 7 ON CC40	BC STOP WHILING RUNNING BC SIGNAL MISSING/	PLC POWER RECYCLED	21:45:00	21:50:00	