



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 23/07/2026

Incharge(s): G Eswara Rao

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 29	TRIPPED ON OLR	RESET DONE 2 TIMES	03:50:00	04:00:00	
2	OHP	TT 1	CHUTE VIBRATOR NOT WORKING/MPCB TRIPPED	MPCB MADE ON	00:20:00	00:45:00	
3	OHP	CO 26	TRIPPED ON OLR	RESET DONE	23:50:00	00:00:00	
4	OHP	CO 84	BRS ACTING DUE TO BELT PIECE	RESET DONE AFTER REMOVE THE BELT PIECE	00:55:00	01:00:00	
5	OHP	BRC 3 ON CO 33M	LT NOT TAKING PLACE/PCRD TENSION ACTED	CABLE TENSION RELEASED	03:30:00	03:40:00	
6	OHP	RSCO 1A TO SB 3A BUNKAR	POSITION SIGNAL NOT GETTING/ SELECTOR SWITCH NOT WORKING	BYPASSED	22:40:00	23:05:00	SELECTOR SWITCH TO BE REPLACED
7	OHP	CO 48	TRIPPED ON OLR	RESET DONE	04:55:00	05:00:00	
8	OHP	TT 2 AND TT 3	CHUTE VIBRATORS NOT WORKING IN PLC	TO BE CHECKED	23:20:00	00:00:00	
9	CHP	SCR 2 ON CC 33	LT NOT TAKING PLACE/TENSION ACTED DUE TO CABLE FALLEN ON THE GROUND BECAUSE OF GUIDE PROBLEM	WINDING DONE THEN OK	22:55:00	23:10:00	
10	CHP	SCR 9 ON CC 213	BC NOT RUNNING/MPD TRIPPED ON SP FAULT	RESET DONE	04:05:00	04:20:00	
11	CHP	CC 52	MPD TRIPPED ON OLR	RESET DONE	00:35:00	00:40:00	