



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 04/05/2026

Incharge(s): Amit Roy

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	BRC on CO-30	Festoon cable got cut due to mechanical walkaway fell down	Cable rejoining done and tested okay	15:20:00	17:15:00	
2	OHP	CO-26	Reported tripped	OLR acted.Reset done	18:11:00 20:05:00 21:10:00	18:20:00 20:14:00 21:20:00	
3	OHP	CO-8A	BRS malfunctioning	Sensors alignment done and tested okay	14:10:00	14:35:00	
4	OHP	CO-16	Reported tripped	OLR acted.Reset done	21:15:00	21:20:00	
5	CHP	Cc-27A on CC-39	Position indication not coming	Sensor got bent.Repositioned and tested okay	15:30:00	15:40:00	
6	WT	CO-4 (C/D)	Reported not moving	Stop PB high wire came out.Reconnected and tested okay	20:15:00	20:25:00	