



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 05/08/2026

Shift: A

Incharge(s): P Venkat Kiran,P Venkat Kiran

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	brc-4 on co-8a	all drives are not working	acb is in OFF condition. made on and trail run of BRC is taken.	09:40:00	09:55:00	
2	OHP	wobr-2 on co-29	slew not working	wrong complaint	12:30:00	12:40:00	
3	OHP	brc-5 on co-32	Pump is not starting	control mcb was in trip condiition.	11:00:00	11:10:00	made on and trail run taken,.
4	OHP	co-8	Rphase cable side lug got melted, relugging is done	trail run is taken and observed balance currents.	06:00:00	07:15:00	
5	CHP	cc-131	olr acted	reset done	09:15:00	09:20:00	
6	CHP	cc-33 scr-2	lt not taking place	pcrd drum sensor acted. reset done	07:10:00	07:20:00	
7	CHP	scr-9 on cc-104	slew not working	slew pump air blast cooler trip. reset done and slew done.	10:10:00	10:20:00	
8	WT	co-3	tripped on olr	reset done.	07:30:00	07:35:00	while jamming is being cleared.