



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 11/08/2026

Incharge(s): M Kailash

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-5A	ZSS not healthy. Found cable damaged	Proper jointing done and made OK	15:55:00	16:15:00	
2	OHP	CO-26	Overload acted	Reset done	19:25:00 21:00:00	19:35:00 21:10:00	
3	OHP	BRC ON CO-8A	Bucket wheel 1 not rotating. Found CP-1 acting	Informed to mechanical and operation	19:30:00	19:40:00	
4	OHP	BRC ON CO-32	Lt not taking place. PCRD Overtension acted. Checked and found pendulum switch contact not coming	Bypassed in panel. Provide loop and later rectified and kept in circuit	14:40:00	15:30:00	
5	CHP	CC-50	Stopped on ZSS.	kept under observation. Found no problem	18:45:00	19:00:00	
6	CHP	CC-58	Tripped	Reset done	18:30:00	18:45:00	
7	CHP	CC-131	Tripped on overload	Reset done	18:50:00 20:10:00	19:00:00 20:20:00	
8	CHP	CC-54	Tripped on overload	Reset done	19:30:00	19:35:00	