



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 08/10/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	co 111(B)	mpcb tripped,material jamming	made on	14:15:00	14:20:00	2 times
2	OHP	CO 48	olr acted	reset	20:05:00	20:10:00	
3	OHP	BRC on co 32	LT not working,Ot acted	OT released	15:00:00	15:15:00	
4	OHP	tbs 6 on CO7A	right Luff not working,down limit stucked	released	15:20:00	15:40:00	
5	OHP	TBS on CO 20	LT brake not working	checked and found all ok brake got magnetized	19:25:00	19:40:00	
6	OHP	brc on co 28	all drive not working,acb triped	made it on	19:45:00	19:55:00	
7	OHP	CO 26	OLR acted	reset	17:10:00	17:20:00	
8	CHP	CC 35 STK2	LT not working,pcrd cable unwinded,gearbox problem	informed mech	14:50:00	15:05:00	
9	CHP	CC 105 scr 10	b/c not working,signal missing,coal jamming near yard interlock cage	yard zss interlock kept in ckt,informed operation for jamming	18:35:00	18:55:00	
10	CHP	RG1	tripped,gear box problem	mechanical work going on	18:25:00	18:35:00	