



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 05/07/2026

Incharge(s): K SANKARA RAO

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WOBR ON CO-6A	REPORTED LT NOT TAKING PLACE FOUND SELECTION PROBLEM	SELECTOR SWITCH PROPERLY KEPT REMOTE MODE THAN OK	12:30:00	12:50:00	
2	CHP	CC-28 F/G	OLR ACTED (2TIMES)	RESET DONE	07:30:00 10:45:00	07:35:00 10:50:00	
3	CHP	CC-28	OLR ACTED	RESET DONE	08:00:00	08:05:00	
4	CHP	CC-29	B/S ACTED DUE TO BELT OFFCENTERING	B/S BYPASSED OPERATION REQUIREMENT	09:15:00	09:20:00	
5	CHP	CC-52	MPD TRIP	RESET DONE	11:00:00	11:05:00	
6	CHP	CC-106	LT NOT TAKING PLACE M-1 OLR ACTED	RESET DONE	09:30:00	09:40:00	
7	CHP	CC-213 SCR-9	B/C MPD TRIP	RESET DONE	10:10:00	10:20:00	
8	CHP	CC-107	OLR ACTED	RESET DONE	11:50:00	11:55:00	
9	CHP	OP-6	COLOM-NO-14 BOTAM BUS-BAR INSULATOR E/F	REMOVED AND PACKING PROVIDED	13:00:00	13:30:00	
10	CHP	CC-213 SCR-9	B/C STOPPING ON ZSS FOUND ZSSS CAGE TWILTED AND PROBE DAMAGED	ZSS CAGE KEPT CORRECT POSITION AND ZSS PROBE REPLACED WITH NEW ONE THAN OK	13:45:00	14:00:00	
11	WT	OC 1A (c)DRIVE	REPORTED NOT TAKING PLACE	MOTOR BURNT DUE TO JAMMING	11:00:00	11:30:00	
12	WT	OP-6	COLAM NO -4 B PHASE TERMINAL FIXING BLOCK DAMEGED	TEMPORARY TIE WITH WIRE	13:00:00	13:30:00	