



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 22/06/2026

Shift: B

Incharge(s): K SANKARA RAO

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	brc on co-28	reported b/c not running found e/stop acted	RELEASED	16:40:00	16:50:00	
2	OHP	BRC ON CO-28	B/C OLR ACTED	RESET DONE	18:05:00	18:20:00	
3	OHP	BRC ON CO-30	B/W-1 NOT RUNNING FOUND OLR PLUG LOOSE	PROPERLY FIXED THAN OK	19:00:00	19:15:00	
4	OHP	CO 3A	BRS GLASS FUSE BLOWN	REPLACED	15:00:00	15:10:00	
5	CHP	BRC ON CO-30	CT NOT TAKING PLACE CHAIN GOT CUT	INFORMED TO MECHANICAL	19:20:00	19:35:00	
6	CHP	CC-203	OLR ACTED	RESET DONE	14:30:00	14:35:00	
7	CHP	SCR 3 ON CC 37	SLEW OIL LEAKAGE	INFORMED TO MECH	16:40:00 21:15:00	16:50:00 21:25:00	
8	CHP	CC 107	OLR ACTED	RESET	19:25:00	19:30:00	
9	CHP	CC 52	FEEDING CONV OLR ACTED	RESET	16:00:00	21:00:00	4 TIMES
10	CHP	CC 54	OLR ACTED	RESET	15:00:00	21:00:00	5 TIMES
11	CHP	CC 203	OLR ACTED	RESET	14:30:00	14:40:00	
12	CHP	CC-52	MPD TRIP (4TIMES) FEEDING CONVEYOR STOP	RESET DONE	16:15:00	21:05:00	
13	WT	OT-3	DRIVE-2 TRIP ENCODER FAULT	RESET DONE	20:45:00	20:50:00	