



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 26/05/2026

Incharge(s): G Eswara Rao

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS ON CO 7A	LT NOT TAKING PLACE	CONTROL MADE ON AT CABIN	11:10:00	11:30:00	LT NOT STOPPING ON LOAD /INFORM TO MECH .AND ADJUSTED
2	OHP	WOBR ON CO 29	BC NOT RUNNING/CONTROL OFF DUE TO LOWER CUTTING	LUFFING UP DOWN THEN OK	06:35:00	06:45:00	
3	OHP	WOBR ON CO 29	LT NOT TAKING PLACE/CABLE TENSION ACTED	MECH .PROBLEM EXISTING NO GEAR BOX/ RELEASED NO CABLE ON THE DRUM	11:55:00	12:00:00	
4	CHP	SCR 1 ON CC31	BC SIGNAL MISSING/2 TIMES	LT DONE THEN OK	07:00:00	07:20:00	
5	CHP	CC 58	TRIPPED ON OLR	RESET DONE	07:40:00	07:50:00	
6	CHP	CC II4	REPORTED FAIL TO START	DIDNT FOUND ANY PROBLEM NEUTRAL MISSING AT MODULE	12:50:00	13:10:00	SLIDING CONTACTS TO BE CHECKED
7	CHP	SCR 1 ON CC31	LT NOT TAKING PLACE	PCRD TENSION ACTED/RELEASED	06:45:00	07:00:00	
8	CHP	SCR 2 ON CC33	PCRD DRUM FAST SIGNAL ACTED	RESET DONE	07:15:00	07:35:00	
9	CHP	CC 125	TRIPPED ON OLR	RESET DONE	08:20:00	08:25:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 26/05/2026

Incharge(s): G Eswara Rao

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
10	CHP	SCR 10 ON CC105	LT NOT TAKING PLACE/TENSION ACTED	TENSION RELEASED	09:55:00	10:10:00	
11	WT	OT 3	DRIVE 1 TRIPPED ON ENCODER FAULT	RESET DONE	13:35:00	13:40:00	