



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 10/06/2026

Shift: A

Incharge(s): K SANKARA RAO

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS ON CO-7A	REPORTED L/B NOT RUNNING FOUND BOTH B/C OFF CONDITION	MADE ON THAN OK	11:15:00	11:25:00	
2	CHP	CC-203	OLR ACTED	RESET DONE	11:05:00	11:10:00	
3	CHP	CC-51	MPD TRIP (FEEDING CONVEYOR)	RESET DONE	09:45:00	09:50:00	
4	CHP	CC-31,SCR-1	B/C SIGNAL MISSING	LT FWD DONE THAN OK	07:10:00	07:20:00	
5	CHP	CC-31,SCR-1	SIGNAL MISSING	PLC POWER AND CONTROL RE-CYCLED THAN OK	07:50:00	08:00:00	
6	CHP	CC-40, SCR-7	LT NOT TAKING PLACE	WRONG COMPLAINT	09:20:00	09:25:00	
7	WT	OP-2	DRIVE-3 OLR ACTED	RESET DONE	12:00:00	12:15:00	