



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 25/05/2026

Shift: A

Incharge(s): G Eswara Rao

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	BRC ON CO 8A	NO DRIVES/MCB 110V AC NEUTRAL LOOPING WIRE GOT MELTED IN PLC PANEL	TEMPORARLY BYPASSED AND GIVEN CLEARANCE	09:20:00	10:15:00	MCB MELTED
2	OHP	CO 13 B/D	TRIPPED ON OLR	RESET DONE	07:15:00	07:25:00	
3	CHP	CC 201	TRIPPED ON OLR	RESET DONE	12:30:00	12:40:00	
4	CHP	SCR 10 ON CC 105	L T NOT TAKING PLACE/CABLE SUBMERGED IN THE MATERIAL	CABLE REMOVED FROM THE MATERILA	10:20:00	10:40:00	
5	CHP	SCR 3 ON CC 37	BC NOT RUNNING/30 DEGREE LIMIT ACTED	RESET DONE	12:00:00	12:15:00	
6	CHP	CC 125	TRIPPED ON OLR	RESET DONE	13:10:00	13:25:00	
7	CHP	CC 44	TRIPPED ON OLR	RESET DONE	13:15:00	13:25:00	
8	CHP	SCR 3 ON CC37	LT NOT RUNNING	M1 TRIPPED ON OLR/RESET DONE	13:30:00	13:45:00	
9	CHP	CP 2	F/REVERSE NOT TAKING PLACEACB	ACB TRIPPED AT COL.NO 24 DUE TO BOTTOM AND TOP C CLAMPS LOOSE/CLAMPS TIGHTEN PROPERLY THEN TESTED OK	11:50:00	12:00:00	
10	CHP	TT 3 ON BPC 1	SIGNAL MISSING/CABLE GOT CUT AND GLSS FUSE BLOWN ,SENSOR NOT WORKING	BYPASSED I/O RACK	11:00:00	11:10:00	TO BE KEPT IN CKT
11	WT	OP 2	F R/REVERSE NOT TAKING PLACE/ACB TRIPPED AT COL.NO 31	ACB MADE ON AND TESTED OK	11:00:00	11:10:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 25/05/2026

Incharge(s): G Eswara Rao

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
12	IOSA	WOBR ON OC 18A	LUFFING NOT TAKING PLACE/DOWN LIMIT ACTED	MECH.OPERATED IN LOCAL MODE FOR MECH WORK/LIMIT RELEASED BYMANUALY THEN OK	09:10:00	10:30:00	