



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 21/09/2026

Incharge(s): Amit Roy,K SANKARA RAO

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	brc on co-32	REPORTED LT NOT TAKING PLACE FOUND M-4 OLR ACTED	RESET DONE	23:05:00	23:20:00	
2	OHP	CO-10A	OLR ACTED (2TIMES)	RESET DONE	00:30:00 03:10:00	00:40:00 03:20:00	
3	OHP	CO-29	OLR ACTED	RESET DONE	04:10:00	04:20:00	
4	OHP	CO36	OLR ACTED	RESET DONE	05:00:00	05:10:00	
5	OHP	WOBR ON CO-26	REPORTED ALL DRIVES NOT WORKING FOUND PLC CARD (XA04) FAULTY	REPLACED THE CARD THAN OK	01:15:00	04:10:00	
6	CHP	CC-131	OLR ACTED (2TIMES)	RESET DONE	00:55:00 04:50:00	01:00:00 04:55:00	
7	CHP	CC-58	TRIPPED ON CURT SP FAULT	RESET DONE	05:25:00	05:45:00	