



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 28/04/2026

Incharge(s): G Eswara Rao

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS ON CO19	LT THRUSTER BRAKES ARE NOT WORKING/SINGLE BRAKE IS WORKING BUT BRAKE SHOES WARNOUT TO BE CHANGED	INFORM TO MECH.	11:30:00	11:50:00	
2	OHP	BRC ON CO 34	BC DIRECTION CHANGED FOR OPERATION REQUEST	CHANGED AND AGAIN NORMALISED	08:20:00	09:15:00	
3	OHP	CO 26	TRIPPED ON OLR	RESET DONE	07:40:00	07:45:00	
4	CHP	CC213	TRIPPED ON OLR IN MPD	RESET DONE	06:30:00	06:40:00	
5	CHP	SCR 1 ON CC31	LT NOT TAKING PLACE/PCRD CABLE TENSION ACTED	TENSION RELEASED	07:00:00	07:10:00	
6	CHP	SCR 7 ON CC39	LT NOT TAKING PLACE/DRIVE TRIPPED ON OLR	RESET DONE	08:45:00	08:55:00	
7	CHP	SCR 10 ONCC105	SLEW NOT TAKING PLACE/30DEGREE LIMIT ACTED	LIMIT RELEASED	11:30:00	11:40:00	
8	CHP	SCR 8 ON CC112	LUFFING LOWER LIMIT BYPASSED FOR OPERATION REQUIREMENT	AFTER CLEARANCE AGAIN KEPT IN CKT	11:55:00	13:30:00	
9	CHP	SCR 6 ON CC106	HIGH SPEED RELAY TRIPPING	I/O PANEL AND COUPLER SIDE CHECKING DONE MACHINE SIDE 20 MEGA OMS,AND PANEL SIDE 5,10,5 MEGA OMS FROM COUPLER	06:30:00	07:45:00	