



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 17/09/2026

Shift: C

Incharge(s): Amit Roy,K SANKARA RAO

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	VS-2	OLR ACTED	RESET DONE	23:55:00	00:00:00	
2	OHP	BRC ON CO-28	B/W-1 OLR ACTED	RESET DONE	00:30:00	00:50:00	
3	OHP	CO-26	OLR ACTED	RESET DONE	02:00:00	02:10:00	
4	OHP	TBS ON CO-21	REPORTED LT NOT TAKING PLACE FOUND DRIVE TRIP	RESET DONE	02:30:00	02:50:00	
5	OHP	CO-29	OLR ACTED (2TIMES)	RESET DONE	02:50:00 04:35:00 05:40:00	03:00:00 04:45:00 05:50:00	
6	OHP	WOBR ON CO-6A	B/C ZSS MODULE PROBLEM	ZSS MODULE AND SENSOR REPLACED THAN OK	22:00:00	22:40:00	
7	OHP	CC-131	OLR ACTED	RESET DONE	02:20:00	02:25:00	
8	OHP	CO-29	OLR ACTED	RESET DONE	05:40:00	05:50:00	
9	OHP	CO-42A TO CO-43A	CHUTE VIBRATOR POWER CABLE INSULATION DAMAGE	PROPERLY INSULATED THAN OK	22:40:00	22:50:00	
10	OHP	BRC ON CO-30	B/C NOT RUNNING	OLR ACTED AND E-STOP ACTED AT MCC SIDE.OLR RESET DONE AND E-STOP RELEASED AND TESTED OKAY	02:20:00	02:45:00	
11	CHP	S-2 ON CC-35	B/C TRIP ON UNB FAULT (4TIMES)	RESET DONE	22:25:00	03:15:00	
12	CHP	SCR-4 ON CC-111	REPORTED B/C NOT RUNNING FOUND C/S ACTED DUE TO DISCHARGE CHUTE JAMMING	INFORMED TO OPERATION	00:50:00	01:05:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 17/09/2026

Shift: C

Incharge(s): Amit Roy,K SANKARA RAO

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
13	CHP	SCR-1 ON CC31	REPORTED LT NOT TAKING PLACE FOUND PCRD O/T ACTED	RELEASED THAN OK	05:25:00	05:35:00	
14	WT	CP-2	REPORTED NOT MOVING	LC-10A POE AND ETHERNET CABLE TO ANTENNA FOUND DAMAGED DUE TO WATER.POE CHANGED AND CABLE DAMAGED PORTION REMOVED,CRIMPED AND PLUGGED.PUSHER MOVEMENT DONE AND TESTED OKAY	05:00:00	06:00:00	
15	IOSA	WOBR (FLS)	LT NOT TAKING PLACE PCRD O/T ACTED	RELEASED THAN OK	02:35:00	02:55:00	