



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 25/08/2026

Incharge(s): P Venkat Kiran,P Venkat Kiran

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	co-33m	olr acted	reset done	07:00:00	07:10:00	
2	OHP	co-33m	zss acting, probe problem,	replaced probe and tested.	09:10:00	09:30:00	
3	CHP	scr-7 on cc-40	luff not taking place	filter clog acted. reset done and informed mechanical	06:30:00	07:00:00	
4	CHP	scr-7 on cc-40	BC no starting ; slew 30 degree limit acted twice	reset done	08:30:00 12:30:00	08:40:00 12:40:00	
5	CHP	scr-3 on cc-37	bc tripped on curt sp fault	reset done	10:40:00	10:45:00	
6	CHP	cc-125 cjd	reported acting frequently	coal heaps touching the sensor, cleaned material .	11:25:00	11:35:00	