RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 12/11/2026

Shift: B

Incharge(s): Nagendra Midde

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-25	overload acted	Reset done	18:22:00	18:30:00	
2	OHP	CO-5A	BRS acting frequently. checked and found OK	.	21:30:00	21:40:00	
3	CHP	STK-2 ON CC-112	B/C not running. MPR tripped	Reset done	14:25:00	14:40:00	
4	CHP	SCR-1 ON CC-31	Slew not working. Found slew drive tripped	reset done	17:30:00	17:45:00	
5	CHP	CC-108	overload tripped	Reset done	17:00:00 20:45:00	17:05:00 20:50:00	
6	CHP	SCR-6 ON CC-38	slew not working. slew area coal jamming.	informed to operation	19:35:00	19:50:00	
7	CHP	SCR-3 ON CC-106	B/C not running in GVM side. checked and found COB-5 HMI bed selection not proper	Made proper selection and checked OK	18:35:00	19:10:00	
8	CHP	SCR-3 ON CC-106	LT not working. Drive tripped	Reset done	21:20:00	21:35:00	
9	CHP	CC-131	overload tripped	Reset done	18:15:00 20:40:00	18:20:00 20:45:00	
10	CHP	CC-54, CC-130,CC-131	Belt sway bits became RED. checked in PLC and found no complaint	checked in field and found Belt sway switches acted. Released	19:10:00	19:40:00	
11	WT	OP-3	No movement. Found D-5 rotor contactor stuck up.	contactor opened and cleaned.	14:00:00	14:15:00	