वी.एस.पी
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

## VISAKHAPATNAM STEEL PLANT

### RAW MATERIAL HANDLING PLANT

### ELECTRICAL SHIFT REPORT

Date: 01/11/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|---|---|---|---|---|---|---|---|
| 1 | OHP | wobr on co 29 | LT and luffing not working,M2 olr acted | reset | 16:55:00 | 17:10:00 | |
| 2 | OHP | CR1 | showing red,mpr olr acted | reset | 18:05:00 | 18:10:00 | |
| 3 | OHP | VF 10A | olr acted | reset | 20:00:00 | 20:15:00 | |
| 4 | CHP | CC 40 scr7 | BC not running,signal problem,signal gone 2 times | LT done than ok but again signal problem came | 19:00:00 | 19:30:00 | |
| 5 | CHP | CC 51 | mpd acted | reset | 15:35:00 | 15:40:00 | |
| 6 | CHP | CC 131 | motor tripped 2 times | reset | 14:35:00 | 14:40:00 | |
| 7 | WT | OP9 | no communication, | POE power recycle done in OP9 | 20:15:00 | 20:35:00 | |
| 8 | WT | OP2 | no movement,power ok | pusher @parking zone,middle phase power not coming,@col 4 from parking zone to trolley line temporary bolt tightened than power holding | 20:28:00 | 21:20:00 | |