



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 11/08/2026

Shift: A

Incharge(s): G Eswara Rao

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 26	TRIPPED ON OLR twice	RESET DONE	07:40:00 08:20:00	07:50:00 08:25:00	
2	OHP	TIS 4 ON CO 44	NOT RUNNING/OLR ACTED AND CO 44 BELT OFFCENTREING and OBSTRUCTING THE TIS BELT	RESET DONE AFTER MECH.ADJUSTMENT	07:10:00	07:25:00	
3	OHP	CO 50	TRIPPED ON OLR	RESET DONE	08:05:00	08:15:00	
4	OHP	TBS ON CO 7A	LT NOT TAKING PLACE/DRIVE NOT STARTING AND SHOWING LVO FAULT,	CHECKED AND FOUND POWER CONTACTOR O/G TERMINATION GOT LOOSE AND SELECTOR IN BYPASS MODE/ALL TERMINATIONS TIGHTEND,KEPT IN REMOTE MODE	09:40:00	10:50:00	
5	OHP	CO 10A	ZSS ACTING/RETURN WIRE LOOSE IN ZSS MODULE TB	ALL WIRES TIGHTEND IN TB THEN OK	11:05:00	11:30:00	
6	OHP	TBS ON CO 19	RIGHT LUFFING NOT WORKING /OLR ACTED	RESET DONE	11:10:00	11:20:00	
7	OHP	BRC ON CO 8A	NO DRIVES RUNNING/ACB TRIPPED	ACB MADE ON	13:20:00	13:30:00	
8	CHP	CC-12	bss acted due to offcentering	bss adjusted on operation requirement and reset done	09:45:00	09:55:00	
9	WT	CP 1	F/R NOT TAKING PLACE/COMMUNICATION FAULT	RESET DONE	07:00:00	07:55:00	
10	WT	CP 4	F/R NOT TAKING PLACE/ MICROLOGIC PLC in LC10A communication PROBLEM. Ethernet cable connected properly and tested.	RESET DONE	10:00:00	10:40:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 11/08/2026

Incharge(s): G Eswara Rao

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
11	WT	AF 4	NOT RUNNING/DRIVE TRIPPED	POWER AND CONTROL RECYCLED	11:45:00	12:00:00	
12	WT	OT 5	F/R NOT TAKING PLACE/TOP LAMP LS 2	KEPT BYPASS IN SCADA	12:20:00	12:30:00	