



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 12/05/2026

Shift: A

Incharge(s): G Eswara Rao

| Sl No | Area | Equipment       | Problem                                            | Action                          | From                 | To                   | Remarks           |
|-------|------|-----------------|----------------------------------------------------|---------------------------------|----------------------|----------------------|-------------------|
| 1     | OHP  | CO 16           | TRIPPED ON OLR DUE TO DECK SHEETS JAMMING /3 TIMES | RESET DONE AND TESTED OK        | 06:30:00             | 10:00:00             |                   |
| 2     | OHP  | BRC ON CO 33M   | BW1 NOT RUNNING/BW STUCKUP WITH STONE              | INFORM TO OPERATION             | 06:50:00             | 07:00:00             | MOTOR IS RUNNING  |
| 3     | OHP  | CO 6            | PC ACTED /NOT GETTING RESET BY OPERATION           | BYPASSED AT CJB                 | 12:25:00             | 12:40:00             | TO BE KEPT IN CKT |
| 4     | OHP  | CO 85           | TRIPPED ON OLR                                     | RESET DONE                      | 06:45:00             | 06:50:00             |                   |
| 5     | CHP  | SCR 4 ON CC 32  | LT NOT TAKING PLACE/PCRD CABLE TENSION ACTED       | TENSION RELEASED/2 TIMES        | 06:40:00<br>08:50:00 | 06:50:00<br>09:00:00 |                   |
| 6     | CHP  | SCER 3 ON CC 33 | LT NOT TAKING PLACE                                | DRIVE TRIPPED ON OVD/RESET DONE | 06:40:00             | 06:50:00             |                   |
| 7     | CHP  | CC 125          | TRIPPED ON OOLR /2 TIMES                           | RESET DONE                      | 09:20:00<br>12:20:00 | 09:25:00<br>12:25:00 |                   |
| 8     | CHP  | SCR 2 ON CC 33  | LT NOT TAKING PLACE/PCRD DRUM OVER SPEED CATED     | RESET DONE AT CABIN PLC         | 10:50:00             | 11:00:00             |                   |
| 9     | CHP  | S2 ON CC 106    | SLEW NOT TAKING PLACE DUE TO JAMMING               | INFORM TO OPERATION             | 11:50:00             | 12:00:00             |                   |
| 10    | CHP  | SCR 2 ON CC 33  | BW NOT RUNNING/E.PB OPERATED                       | PB RELEASED                     | 13:00:00             | 13:20:00             |                   |
| 11    | WT   | OT 3            | D1 TRIPPED ON FAULT CODE 7                         | RESET DONE/2TIMES               | 10:30:00<br>12:50:00 | 10:35:00<br>12:55:00 |                   |



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 12/05/2026

Incharge(s): G Eswara Rao

Shift: A

| Sl No | Area | Equipment | Problem                                 | Action     | From     | To       | Remarks |
|-------|------|-----------|-----------------------------------------|------------|----------|----------|---------|
| 12    | WT   | OP 8      | F /R NOT TAKING PLACE/D2 TRIPPED ON OLR | RESET DONE | 12:35:00 | 12:45:00 |         |