



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 11/09/2026

Shift: B

Incharge(s): Nagendra Midde

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	BRC ON CO 8A	NO DRIVES RUNNING/ACB TRIPPING DUE TO RAIN WATER LEAKAGE IN BREAKER PANEL	ALL PANELS COVER WITH MATS	15:30:00	17:00:00	
2	OHP	BRC ON CO 8A	BC NOT RUNNING/Y PHASE GOT EARTH FAULT AT PANEL O/G	POWER CABLE Y PHASE INSULATION DONE THEN TESTED OK	17:15:00	18:50:00	
3	OHP	CO 47	ZSS ACTING	PROBE REPLACED THEN OK	14:05:00	14:30:00	
4	OHP	CR 1	TRIPPED ON OLR	RESET DONE	19:15:00	19:20:00	
5	OHP	CO 25	TRIPPED ON OLR	RESET DONE	14:45:00	14:55:00	
6	OHP	CO 34	TRIPPED ON OLR	RESET DONE	20:00:00	20:05:00	
7	OHP	CO 34	BRS ACTING /CABLE EARTH FAULT	BYPASSED AT CJB	16:25:00	16:40:00	
8	OHP	CO 26	TRIPPED ON OLR	RESET DONE	21:00:00	21:10:00	
9	OHP	BRC ON CO 8A	CT NOT TAKING PLACE/CHAIN GOT CUT	INFORM TO OPERATION	21:30:00	21:40:00	
10	CHP	CC 54	TRIPPED ON OLR	RESET DONE	14:20:00	14:25:00	
11	CHP	CC 35 ZSS	Cable cut Near module	Rejoined	15:00:00	15:15:00	
12	CHP	SCR 5 on CC 32 LT	M2 trip	Reset	18:45:00	19:00:00	
13	CHP	CC 37 ZSS	Cable got cut Near module	Connected properly	19:00:00	19:15:00	
14	CHP	SCR on CC 36 B/C	Slew 30 degree limit acted	Released	19:40:00	19:55:00	
15	CHP	CC 26 FLAP GATE	TRIPPED ON MPCB	MADE ON	14:15:00	14:30:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 11/09/2026

Incharge(s): Nagendra Midde

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
16	CHP	CC 202	DRIVE TRIPPED ON OLR	RESET DONE	16:25:00	16:35:00	
17	CHP	SCR 2 on CC 33	Modem to plc not communicating	Ethernet connections tightened then ok	19:30:00	20:00:00	
18	CHP	Scr 3 on CC 36 B/C	Modem supply Neutral got cut	Reconnected Properly	20:00:00	20:20:00	
19	CHP	CC 12	BRS ACTED	RESET DONE	18:25:00	18:30:00	
20	CHP	CC 28	FLAP GATE /MPCB TRIPPED	MADE ON	15:45:00	15:55:00	